

FIELD INSPECTION REPORT

Date of Inspection :	28/12/20	District:	East Champaran
Division :	Motikani	Length (km):	1.474 Km
Name of the Road:	NH-28 To Ladparga		
Scheme/Programme:	MAINTENANCE	PMU SY	
Package No.:	RA-11A-599	Road Id No.:	-
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRU)	✓SRU
Unsatisfactory (U)	

NAME: Rajendra Pr. Yadav

DESIGNATION: A-E

28/12/20

(Signature)

Rajendra Pr. Yadav