

FIELD INSPECTION REPORT

Date of Inspection :	28/12/20	District:	East Champaran
Division :	Motihari	Length (km):	1104.9 Km
Name of the Road:	Loyt Kenu Road To Dawadristia		
Scheme/Programme:	MAINTENANCE	PMUSY	
Package No.:	BA-11A-603	Road Id No.:	—
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRU/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRU)	
Unsatisfactory (U)	

NAME: Baidyanath K.

DESIGNATION: J.E

(Signature)
02/10/12-1