

FIELD INSPECTION REPORT

Date of Inspection : 10/12/20		District: East Champaran
Division : Mofidhar		Length (km): 2.136 km
Name of the Road: PWD Areray To Koberga		
Scheme/Programme: MAINTENANCE		PMU Sy
Package No.:		Road Id No.: —
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4. Compliance History		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rajendrakumar
DESIGNATION: A-E

(Signature)
Rajendrakumar
12/12/20