

# FIELD INSPECTION REPORT

Date of Inspection :		District: SAMASTIPUR
Division : SAMASTIPUR		Length (km):
Name of the Road: LOST Kalya Chok to Bhona Chok Sikkara Chok		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:		Being/Completed/Under Maintenance
Work is a case of:		Connectivity/Up gradation/ Maintenance
Sl. No.		Parameters to be checked
1.	Pavement	Remarks
a)	Road Junction	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joint provided or not (CC Pavement)	Yes/No
g)	Compaction of topsoil & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of headwalls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings, approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards, informative/cautionary Board/km & 200m markings are provided and maintained	Yes/No
4.	Compliance His	
a)	Status of ATR's	NEL

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sprayan  
(Signature) 21

NAME: SPRAYAN KR. SINGH