## FIELD INSPECTION REPORT

Date of Inspection: 6/01/ >			District: Kathlar	
			Length (km): 0.622	
Vame of	the Road: 7	01 70	Kewatiya Santhal	itola
Scheme/	Programme:	MAINTENAN		
Package			Road Id No.:	
	f the Project:		leted/Under Maintenance	
Work is	a case of:		ity/Up gradation/ Maintenance	
SI. No.		Paramete:	rs to be checked	Remarks !
1.	Payement		· · · · · · · · · · · · · · · · · · ·	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			<b>√</b> S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of tlank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge 🖆 🗀		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
<b>3</b> .	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	2.

Say 06/01/21.
(Signature)

NAME: SATISH CHAVDHARY

DESIGNATION: A.C.