

FIELD INSPECTION REPORT

Date of inspection: 09/01/2021 District: Nalanda
 Division: H/LS Length (km): 1.010 km
 Name of the Road: PMGSY Ladunai Ke Sznawa more to Nathu Bigla
 Source of Funding: STATE FUND - PMGSY (SE)
 Project No.: PMGSY (SE) Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Completed
 Work is a case of: New Connectivity/Upgradation/Maintenance - New Connectivity

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
1	Road Surface condition	✓ S/U
2	Condition of Surfacing	✓ C/U
3	Rolling Quality	✓ S/U
4	Road Camber	✓ S/U
5	Whether free from defects such as visible cracks, exposed sub-grade in case of RCC Pavement	Yes/No ✓
6	Condition of joints provided or not (RCC Pavement)	Yes/No
7	Condition of Bank/slope & cuttings if any	Yes/No ✓
8.	Cross Drainage	
1	Condition of front walls in Hume pipe culverts including its painting	✓ S/SRI/U
2	Condition of abutments & wing walls slab in RCC culverts	✓ S/SRI/U
3	Condition of footings/slab approach for Bridges	S/SRI/U - N.A.
9.	Road Furniture	
1	Whether sign boards/informative/cautionary Board/km & 200m signs Pavement mark markings are provided and maintained	✓ Yes/No
10.	Compliance History	
11	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Signature
 09/01/2021

Garish Kumar Ranjan