


FIELD INSPECTION/MAINTENANCE

Date of Inspection:	09-01-2021	District:	Gopalganj
Division:	H-1	Length (km):	0.466 km
Name of the Road:	H-1 KUSHAYATI ROAD-10-FORWARDING		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U (S)
b)	Condition of Surfacing	S/U (S)
c)	Riding Quality	S/U (S)
d)	Road Camber	S/U (S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NO)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (Y)
g)	Compaction of flank/slope & raincuts if any	Yes/No (NO)
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - (S)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (S)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U + (S)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No (NO)
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 09/01/2021
 (Signature)

NAME: MANDI KUMAR
 DESIGNATION: Assistant Engineer