

FIELD INSPECTION REPORT

Date of Inspection : 5/12/2020		District: SAMASTIPUR	
Division : SAMASTIPUR		Length (km): 1.010 km	
Name of the Road: S028 Hanuman mandir hajma hila to malang chaur			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		ing/Completed/Under Maintenance	
Work is a case of:		Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction	S/U	
b)	Condition of Surface	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joint provided or not (CC Pavement)	Yes/No	
g)	Compaction of shoulder & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of rail slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign board, Informatory/cautionary Board/km & 200m markings are provided and maintained	Yes/No	
4.	Compliance His		
a)	Status of ATR's	NEL	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature: 5/12/2020

NAME: SPP/PAI KR. SJAIGH