

FIELD INSPECTION REPORT

Date of Inspection : 8-1-21	District: Haldwari
Division : 14) S.C.	Length (km): 0.405 km
Name of the Road: Kailash Nigam, Mumukshu Road to Jaitapur	
Scheme/Programme: MAINTENANCE	Mean km
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S S
b)	Condition of Surfacing	S/S S
c)	Riding Quality	S/S S
d)	Road Camber	S/S S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U C
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U C-
c)	Condition of railings/slab/approach for Bridges	S/SR/U A-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/D

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Pradeep Kumar Singh
S.C.

(Signature)
8/1/21