

FIELD INSPECTION REPORT

| | | |
|-------------------------------|--|-------------------|
| Date Of Inspection 16/12/2020 | | District Bhojpur |
| Division Piro | | Length (km): 1.50 |
| Name of the Road: | Sog to Jamuaon Mahadevt talga. | |
| Scheme/Programme | MAINTENANCE | |
| Package No.: | Road Id No.: 10401812008 | |
| Status of the Project : | Ongoing/Completed/Under Maintenance | |
| Work is a case of : | New Connectivity/Up gradation/Maintenance | |
| SI No. | Parameters to be checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction condition | ✓S/U |
| b) | Condition of Surfacing | ✓S/U |
| c) | Riding Quality | ✓S/U |
| d) | Road Camber | ✓S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | N.A. S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | N.A. S/SRI/U |
| 3 | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 200m Stone & Km Stone Missing. | Yes/No |
| 4 | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | — |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | — |

Name: Bhawesh Pr. Tiwari

(Signature)

Designation: A.E.