

## Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- *Cnyan vibhakar*  
2 Name of Block/Road- *Katoa / Katoa Hama chawle to chammula sthan Hore Hre*  
*Dhamor bus stand*

A ~~For Road~~

- 1 Damage Location/Chainage *0.00m, 0.100m, 0.300m, 0.400m, 0.500m, 0.620m, 2.01m*  
2 Damage Length *1.3032km*  
3 Nature of Damage  
4 Details of Restoration Works-  
i Material being used in Restoration Works- *Brick bats*  
ii Equipments/Tools being used in Restoration Works-  
iii Procedure Taken up in Restoration Works-  
iv Restored Length - *1.3032km*

~~B. For Bridge~~

- 1 Damage Location/Chainage  
2 Damage Length  
3 Nature of Damage  
4 Details of Restoration Works-  
i Material being used in Restoration Works-  
ii Equipments/Tools being used in Restoration Works-  
iii Procedure Taken up in Restoration Works-  
iv Restored Length

Signature of JE/ AE/ EE

*12-12-20*  
Signature

(Name of Inspector)

*EE*

*RWD work Division*  
*Muzaffargarh Gatt-1*

## GENERAL ABSTRACT

Name of Road	Katra Thana Chowk to Chamunda Sthan Hote Hue Dhanor Bus Stand Tak
District	Muzaffarpur
Block	Katra
Division	Muzaffarpur East-2
Length of Road (in Km)	3.188

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	26.896
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	26.896
TOTAL COST OF PROJECT IN LACS =		26.896

say 26.90 lac

*[Handwritten signature]*

**JE**  
**RWD**

AE

AE  
RWD

1/4

EE  
RWD

Technically approved for Rs 26.90 lac  
(Rupees Twenty six lac ninety thousand only)

SE 26.12.20

RWD work circle  
m42affairpug