

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Ketur / Nawaela PWD road to Teenmuhani Bagham Ashan

A. For Road

1. Damage Location/Chainage : 0.500km, 0.530km
2. Damage Length : 0.0562km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Bridge bauls & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.0562km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
18.11.20
Signature

(Name of Inspector)

EE

RWD WORK DIVISION
MURADSHAPUR GATE-1

GENERAL ABSTRACT

Name of Road Nawada PWD Road to Teenmuhan Barham Asthan

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 0.601 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.108
2	Sand Filling	0.222
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	8.330
TOTAL COST OF PROJECT IN LACS =		8.330

Say 8.33 lakh


28/10/2020

JE
RWD



28.10.2020

AE
RWD


21/11

EE
RWD

Technically approved for Rs 8.33 lakh (Rupees Eight lakh
Thirty three thousand only)


28.12.20

SE

RWD work circle
Muzaffarpur