

## Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhakar
- 2 Name of Block/Road- Katsa/Sonpur notali madhy vidalay to Banjari mahadali tola


☒ A For Road

- 1 Damage Location/Chainage 0.00km, 0.0101km, 0.0301km, 0.1001km, 0.301km, 0.5001km, 1.0001km
- 2 Damage Length 0.50911km
- 3 Nature of Damage
- 4 Details of Restoration Works-
  - i Material being used in Restoration Works- Broken bats
  - ii Equipments/Tools being used in Restoration Works-
  - iii Procedure Taken up in Restoration Works-
  - iv Restored Length 0.50911km

☒ B. For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-
  - i Material being used in Restoration Works-
  - ii Equipments/Tools being used in Restoration Works-
  - iii Procedure Taken up in Restoration Works-
  - iv Restored Length

Signature of JE/ AE/ EE

  
Signature  
(Name of Inspector)

EE

RWD WORK Division  
muzaffarpur East -1



### GENERAL ABSTRACT

Name of Road Sonpur Gatoli Madhay Vidalay to Banjari Mahadalit Tola

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 1.370 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	19.831
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	19.831
TOTAL COST OF PROJECT IN LACS =		19.831


say 19.83 lac



JE  
RWD




AE  
RWD



EE  
RWD

Technically approved for Rs 19.83 lac.  
(Rupees nineteen lac eighty three thousand only)



RWD WORK CIRCLE  
MUZAFFARPUR