

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar
2. Name of Block/Road - Katsa / village Palsaul to Dumri REO via Amury road & shop of Dosh Babu Prasad,

A. For Road

1. Damage Location/Chainage : 0.01km, 0.100km, 0.200km, 0.500km, 0.650km, 0.820km
2. Damage Length : 0.1081km (0.10785) 0.90km, 1.101km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.1081km (0.10785)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Shree
21-12-20
Signature

(Name of Inspector)

EG
RWD WORK DIVISION
MUZAFFARPUR CANT-1

GENERAL ABSTRACT

Name of Road Village Pahsaul to Dumari REO Via PMGSY Road & Shop of Dosh Babu Prasad
 District Muzaffarpur
 Block Katra
 Division Muzaffarpur East-2
 Length of Road (in Km) 1.726 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.469
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	1.469
TOTAL COST OF PROJECT IN LACS =		1.469

say 1.47 lac

[Signature]
 JE

RWD

[Signature]
 AE

RWD

[Signature]
 EE

RWD

*Technically approved for Rs 1.47 lac
 (Rupees one lac forty seven thousand only)*

[Signature]
 SE

RWD work circle
 muzaffarpur