

9

Continuation

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3/101	Constn of Reform work				
	by Benchmark				
	vide TMB P 6				
0.755 Km @ R.	10883228				822120
4/1 vis	Constn of Reform pillar				
	by				
	vide TMB P 6				
0.755 Km @ R.	11565207				873220
5/3	Cleaning and grubbing				
	Rock land				
	vide TMB P 6				
0.226 Hect R.	51133276				1156620
6/4	Constn of embankment				
	with land up to				
	1000 m.				
	vide TMB P 6				
181.845 m ³ @ R.	202252				3682720
11/6	Constn of embankment				
	with land up to 1000 m				
	vide TMB P 6				
424.308 m ³ @ R.	16741/m ²				7103320
7/5	Constn of subgrade				
	earthen shoulder				
	with abutment				
	vide TMB P 6				
2091.925 m ³ @ R.	20416/m ³				42708720

Continuation

