

FIELD INSPECTION REPORT

Date of Inspection:	07/01/2021	District:	Sheekhupura
Division:	Sheekhupura	Length (km):	1.50 km
Name of the Road:	Sheekhupura	Year of Construction:	2018
Schema/Programme:	MAINTENANCE	Under Maintenance:	(Under Maintenance)
Package No.:		Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Works a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.	Particulars	Remarks	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
h)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
i)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
j)	Condition of railings/slab/approach for Bridges	S/SRI/U	
k)	Whether sign boards/Informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No	
l)	Status of ATR's & any others		

Raincuts found at some places

Km & 200m S/m not maintained properly.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

07/01/2021
(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A.C.