

FIELD INSPECTION REPORT

Date of Inspection:	07/01/2021	District:	Shivapada
Division:	Shivapada	Length (km):	1.36 KM
Name of the Road:	Firangi bigha More to Firangi bigha		
Scheme/Programme:	MAINTENANCE	MMWS (km) Under Egm. Point	
Package No.:		Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
SP No.		Remarks (if checked)	
1. Pavement			
a) Road Junction condition	✓ S/U		
b) Condition of Surfacing	S/U ✓		
c) Riding Quality	✓ S/U		
d) Road Camber	✓ Yes/No		
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No		
f) Contraction Joints provided or not (CC Pavement)	✓ Yes/No		
g) Compaction of flank/slope & raincuts if any	Yes/No		
2. Cross Drainage			
a) Condition of head walls in Hume pipe culverts including its painting	✓ S/SRU/U		
b) Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRU/U		
c) Condition of railings/slab/approach for Bridges	S/SRU/U M4		
3. Road Furniture			
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
b) Compliance history			
a) Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

NAME: SANGRAM HEMBRON
DESIGNATION: A.E.

Signature
07/01/2021

sign board, km,
200 m Stone not
main road proper
ly.

Raincuts found
at some places.

Not understood
at some places.