## FIELD INSPECTION REPORT

Date of Ir	spection: 07   01   2021   Di	strict: Lalchisora	1	
Division:		ength (km): 0.720	KM	
Name of	he Road: Hals Terfon	Road to Agat		
Scheme/I	rogramme: MAINTENANCE			
Package No.: Road Id No.:				
	the Project: Ongoing/Completed/Un			
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be	checked	Romarks	
1.	Payoment	r i de de la companya		
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		~S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/N		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainago			
a)	Condition of head walls in Hume pipe culverts including its painting		√S/SRI/U	
b)	Condition of Abutment & Wing walls,	Slab in RCC culverts N.A.	S/SRI/U	
c)	Condition of railings/slab/approach for	Bridges N.A.	S/SRI/U	
3.	Road Furniture			
a) ;	Whether sign boards/informatory/car stones/Pavement road markings are pro-		Yes/No	
4.7	Compliance History	The state of the s		

Overall Rating

Status of ATR's & any others

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRS)
Unsatisfactory (U)	

Sq 190 07/01/01

(Signature)

NAME:	