

FIELD INSPECTION REPORT

Date of Inspection :	10/1/2021	District:	Purnia
Division :	Dharmdaha	Length (km)	1.10 km
Name of the Road:	To S to Mushari		Polo Kykrai-
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/ S/U
b)	Condition of Surfacing	S/U /
c)	Riding Quality	/ S/U
d)	Road Camber	/ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	/ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No
g)	Compaction of flank/slope & raincuts if any	/ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Boards/km & 200m stones/Pavement road markings are provided and maintained	Yes/No /
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature) 11/21

NAME: Dharmdaha