

FIELD INSPECTION REPORT

Date of Inspection :	10/1/21	District:	Purnia
Division :	Dhamsaha	Length (km)	5.274
Name of the Road:	Kurni to Duma to		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	/ S/U	
b)	Condition of Surfacing	S/U /	
c)	Riding Quality	S/U /	
d)	Road Camber	/ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No /	
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No	
g)	Compaction of flank/slope & raincuts if any	/ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No /	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

Shailendra Kumar

(Signature) 10/1/21