

FIELD INSPECTION REPORT

Date of Inspection: 7/11/2021		District: Kishanganj	
Division: Kishanganj-1		Length(km):	
Name of the Road: dhaveli main road to kamati state			
Scheme/Programme: MMGSY			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		✓S/U
a)	Road Junction Condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank / shop & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		✓S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		Not ATR

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Sanjeev
7/11/2021
(Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh