

FIELD INSPECTION REPORT

Type of Inspection: 1-1-1		Location: W.R. 11/11	
District: Nimach		Length: 0.5 km	
Name of the Road: Nimach		Road No. 11/11	
Scheme/Programme: Nimach		Road ID No. 11/11	
Status of the Project: Ongoing/Completed/Under Maintenance		Work is a part of: Area Connectivity & road safety Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road surface condition		☒ Yes
b)	Condition of Surfacing		☒ Yes
c)	Riding Quality		☒ Yes
d)	Road Camber		☒ Yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		☒ Yes
f)	Construction Joints provided or not (CC Pavement)		☒ Yes
g)	Compaction of Bank/Slope & raincuts if any		☒ Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m signs/Pavement road markings are provided and maintained		☒ Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

☒ Satisfactory (S)
☐ Satisfactory but requires Improvement (SRI)
☐ Unsatisfactory (U)

Signature: **Adarsh**
 S-01-21
 (Signature)

NAME:

DESIGNATION: