## FIELD INSPECTION REPORT

Dat	te of Inspection :	FIELD INS	PECTION REPORT		
Div	ision: SIMAN	1 1 1	District: SIWAN		
	ne of the Road:	A - 1	Length a		
Sche	eme/Programme:	MAD MAD	Shall		
Pack	age No.:	MAINTENANC			
Statu	s of the Project:	Ongoin - 10	Road Id No.:		
Work is a case of:		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance			
SI. N		Connectivity	y/Up gradation/ Maintenan		
1.	Den	Parameters	to be checked		
avement			Wilder To The Control of the Control	Remark	
a)	Road Junction	condition			
b)	Condition of St		S	S/U	
c)	Riding Quality			S/U	
d)	Road Camber		V	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U		
f)	aggregates in case of CC Pavement.			Yes/No	
g)	provided or not (CC Pavement)			Yes/No	
COLORDINA	compaction of flank/slope & raincuts if any			Yes/No	
	Cross Drainage			1 00/1/0	
1)	Condition of head walls in Hume pine gulvest				
)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
) (	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furniture		S S	S/SRI/U	
V st	Whether sign boa ones/Pavement ro	ards/informatory/ca ad markings are pr	utionary Board/km & 200m ovided and maintained	Yes/No	
C	ompliance Histor	v.	No No		
Sta	atus of ATR's & a	my others			
		- J - MICIO			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
3(0)	V

NAME:

**DESIGNATION:**