

FIELD INSPECTION REPORT

Date of Inspection: 18/12/20		District: Nalanda
Division: Bhabhanip		Length (km): 1.450 km
Name of the Road: Jorai Jaisa Yahi shed to middle school Bannigum village		
Scheme/Programme: MAINTENANCE		
Package No: MWSY		Road Id No:
Status of the Project: Ongoing Completion/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Binding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in flume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: ASHOK KUMAR
DESIGNATION: BE

(Signature) 18/12/20