

MMGSY (GEN) old

Bridgeway Road

FIELD INSPECTION REPORT

Date of Inspection :	07-01-2021	District:	Vaishali
Division :	Mahmud	Length (km):	0.500 km
Name of the Road:	Chakraborty MMGSY to AK Highway Rajahmundry to Chaitanya Road		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		Road Id No.:	31507712049
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI) ✓	SRI
Unsatisfactory (U)	

07.01.2021
(Signature)

NAME: SHROBON KUMAR PRASAD
DESIGNATION: R.W.D. Bidupur