## FIELD INSPECTION REPORT

Date o	of Inspection : C	9.01.21	District: East clamps	rau	
Division: Rexaul			Length (km): 0.919		
Name	of the Road: PA	ID road Ga	imharia to laraling	a a planting most constanting at 20 miles planting at 20	
	e/Programme:		CIE MOSSY	& designation are secured planning. The commences	
Package No.: Road Id No.: 31708512					
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
SI. No.		Parameters to be checked		Romarks	
J.	Pavement				
a)	Road Junction condition			5/1	
b)	Condition of Surfacing			<b>S</b> 1U	
c)	Riding Quality			~S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
ſ)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SPA/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts 4.5/SRI/U				
c)	Condition of railings/slab/approach for Bridges				
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance Hist	ory			
a) :	Status of ATR's &	any others		N.A.	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRII
Unsatisfactory (U)	

NAME: Mithilesh kumar Einst DESIGNATION: Junior Engineer, chauredans