

# FIELD INSPECTION REPORT

|                                                               |                       |
|---------------------------------------------------------------|-----------------------|
| Date of Inspection : 08/1/2021                                | District: NALANDA     |
| Division : HILSA                                              | Length (km): 0.616 Km |
| Name of the Road: Ekangar Radhil to Barsinuda                 |                       |
| Scheme/Programme: MAINTENANCE                                 |                       |
| Package No.: BR-24R-218 (CHGSY)                               | Road Id No.:          |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                       |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                       |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                      |              |
| a)      | Road Junction condition                                                                                              | S            |
| b)      | Condition of Surfacing                                                                                               | S            |
| c)      | Riding Quality                                                                                                       | S            |
| d)      | Road Camber                                                                                                          | S            |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | YES/NO       |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | YES/NO       |
| g)      | Compaction of flank slope & raincuts if any                                                                          | YES/NO       |
| 2.      | <b>Cross Drainage</b>                                                                                                |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U      |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U      |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | -N/A S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | YES/NO       |
| 4.      | <b>Compliance History</b>                                                                                            |              |
| a)      | Status of ATR's & any others                                                                                         | -N/A-        |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory (U)                          | - |

ANJANT KUMAR  
NAME:

(Signature) 08/1/21