

Date of inspection: 08/11/2021
 District: HUDA
 Name of the Road: Changan, Dehlabad Road to Mansinghpur
 Scheme/Programme: MAHATMA
 Package No: (10) 24th 022 (2014/15) Road ID No.
 Status of the Project: ☒ In progress ☐ Completed ☐ Abandoned
 Work is a case of: ☒ New ☐ Extension ☐ Improvement

Sl. No.	Parameters to be checked	Rating
1.	Pavement	
a)	Road Junction condition	5
b)	Condition of Surfacing	5
c)	Riding Quality	5
d)	Road Camber	5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Inspection of flank slope & rainwater if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in these pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing wall. Slope in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 100m stones/Pavement road markings are provided and maintained	YES/NO a few miss
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☒
Unsatisfactory (U)	☐

ANJANT KUMAR
 NAME:

[Signature]
 Date 08/11/21