

FDAR INSPECTION REPORT

Date of Inspection :	08/11/2021	District:	NALANDA
Division :	HUSA	Length (km):	0.650 km
Name of the Road:	Ehangasari Block office to electric office		
Scheme/Programme:	MAINTENANCE		
Package No.:	4515	Road Id No.:	
Status of the Project:	MNP	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	(some part damaged)	S
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		S
f)	Contraction Joints provided or not (CC Pavement)		YES/NO
g)	Compaction of flank slope & raincuts if any		YES/NO
2.	Gross Drainage		
a)	Condition of head walls in culvert pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for bridges		N/A S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		YES/NO
4.	Compliance History		
a)	Status of ATR's & any other		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

INSPECTOR NAME: KUMAR

Signature
(Sign) 08/11/21