

FIELD INSPECTION REPORT

Date of Inspection: 09/11/2021	District: NALANDA
Division: HILSA	Length (km): 0.555 km.
Name of the Road: 1042 Solanpur-Nischalganj Road to Khodabigha	
Scheme/Programme: MAINTENANCE	
Package No.: MA-16514	Road Id No.
Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Rating
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank slope & raincuts if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/pavement road markings are provided and maintained	YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

ANAND KUMAR
NAME:

(Sign: 09/11/2021)