

FIELD INSPECTION REPORT

Date of Inspection: 7.1.2021.	District: Samastipur
Division: RWD Dalsinghsarai	Length(km): 1.310 Km.
Name of Road: L022 to east of Harinagar Gole.	
Scheme / Programme: MAINTENANCE MMGSY(S)	
Package No:	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	S
Unsatisfactory(U)	

NAME:

DESIGNATION:

Heem Chandra Supri
Asst. Engineer
MORU.

(Signature)