

FIELD INSPECTION REPORT

Date of Inspection: 8/01/21
 Division: Sherghol
 District: Grafta
 Name of the Road: Waze more to Kurnak's tohi
 Length (km): 0.70 km
 Scheme/Programme: MAIN ROAD
 Package No.:
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New Connectivity Upgradation/Maintenance

Road Id No.:
 Parameters to be checked

Sl. No.	Pavement	Remarks
1.		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chandradul Sumar

DESIGNATION: T.E.

(Signature)