

FIELD INSPECTION REPORT

Date of Inspection: 08/11/2021 District: NALANDA
 Division: HUSA Length (km): 1.2 KM

Name of the Road: LOTO-TO-4 TO Bhanganon

Scheme/Programme: MAINTENANCE

Package No.: PMGSY (BR-11/287) Road Id No:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Construction/Improvement/Maintenance

Sl. No.	Parameters to be checked	
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank/slope & raincuts if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

ANAND KUMAR
 NAME:

(Signature) 08/11/21