

FIELD INSPECTION REPORT

Date of Inspection :	08/1/2021	District:	NALANDA
Division :	WILSA	Length (km):	0.910 km
Name of the Road:	Telhara Islampur Road to Chhajjipur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MNGSY	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remark
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing BT - Edge cut & loss	U U
c)	Riding Quality	U
d)	Road Camber	U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank/slope & raincuts if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

ANJANI KUMAR
NAME:

(Signature) 08/1/2021