FIELD INSPECTION REPORT

Date of Inspection: 19/12/2010			District: Shutho tu	
Division: Amb shick pun			Length (km): 1467/47	
Name o	f the Road; Lo	35-10 Benjam	5	
	Programme:	MAINTENANC		
Package No.:			Road Id No.:	
			eted/Under Maintenance	
		in the second of	ty/Up gradation/ Maintenance	
Sl. Noi		Parameters	to be cheeked	Remarks
17.4	Payement		Call to the call t	
a)	Road Junction condition			S/W
b)	Condition of Surfacing			S/Ø
c)	Riding Quality			S/U
d)	Road Camber			SAJ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Gross Drain	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/Ú
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
87	e de la	ure		
a)	Whether sign stones/Pavem	Yes/No		
	delomphanee	History -		沙叶中
a)	Status of ATI	R's & any others		

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

AMILKUM

DESIGNATION: AT