

FIELD INSPECTION REPORT

Date of Inspection :		District: 0.600km Sirmastipur
Division : Sirmastipur Block-Tajpur		Length (km): 0.600km
Name of the Road: 702 NH to to Rasbe Alar to No. 12 Sirmastipur		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 32010701302
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'5'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Inspector Name: A2 | Tajpur
NAME:

Signature
12/11/20
(Signature)