


FIELD INSPECTION REPORT

Date of Inspection: 06/01/2021		District: Kishanganj	
Division: Kishanganj-1		Length(km): 0.800	
Name of the Road: Miyapur tegharia road to haji Jamir to Miyapur.			
Scheme/Programme: GTSNY			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	
S1. No	Parameters to be checked		Remarks
1.	Pavement		✓ S/U
a)	Road Junction Condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank / shop & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		✓ S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		Not ATR

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	


 06/01/21
 (Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh