FIELD INSPECTION REPORT

Divisio	31114		District: SIWAN		
	of the Road: G	rambhir pur n	hore to Gambhirh		
Packag	Programme:	MAINTENANC	E		
	of the Project:	Onneis (G	Road Id No.:	2 5.55	
Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
SI. No.		Paramate	y/ op gradation/ Maintenance to be checked	Name of the Party	on the second section of the second
1.	Pavement		w be checked		Remarks
a)	Road Junction	condition		Simon day	distance in the
b)	Condition of Surfacing			5	S/U
				S	S/U
c)	Riding Quality			5	S/U
d)	Road Camber			5	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	80			
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts 5				S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/₽			S/SRI/U	
3.	Road Furnitu	re			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance F	(istory			
a)	Status of ATR	s & any others			

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION: