

# FIELD INSPECTION REPORT


Date of Inspection: 10-1-21		District:- Sheohar
Division:-RWD, Works Div. Sheohar		Length (km):- 1.20 KM
Name of the Road:- SH 54 Langer Chowk to Ubi Ambou Simson Tak		
Scheme/Programme:-		MAINTENANCE MGSY SC
Package No.:-		Road Id No.:-
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railing/slab/approach for bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/No ✓
4.	Compliance History	Only 1 No R.C.C. Culvert Constructed.
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	3RI
Unsatisfactory (U)	

Name:- Dilip Kumar

DESIGNATION:- Junior Engineer

  
 (Signature) 10-1-21