

FIELD INSPECTION REPORT

Date of Inspection:	5-01-21	District:	SARAN.
Division:	SEN AR	Length (km):	0.4 km.
Name of the Road:	SLV Modely Ganga Chat to PMAS Road.		
Scheme/Programme:	RECONSTRUCTION		
Package No.:		Road ID No.:	C.T.S.N.Y.
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/A/p gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/I
b)	Condition of Surfacing	✓ S/I
c)	Riding Quality	✓ S/I
d)	Road Camber	✓ S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

NA

Overall Rating :

- Satisfactory (S)
- Satisfactory but requires Improvement (SRI)
- Unsatisfactory (U)

(Signature)
5-01-21

NAME:

DESIGNATION: