

FIELD INSPECTION REPORT

NDB (Brig)

Date of Inspection :	12-12-2020	District:	Vaithali
Division :	Machmar	Length (km):	0.800 km (A/A ¹ - 1.00 km)
Name of the Road:	Maya P. Amargat Pakari Yogi Sah K. N. K. to Bras K. N. K. to G. S. B. K. N. K.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31507701301
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A S/U
b)	Condition of Surfacing	N.A S/U
c)	Riding Quality	N.A S/U
d)	Road Camber	N.A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N.A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Road Base work complete & other work progress

Note: - G.S.B. and WBM G-II - Satisfactory.

12-12-2020
(Signature)

NAME: SHRABAN KUMAR PRASAD
DESIGNATION: A. E. R. W. D. Bidupur