## FIELD INSPECTION REPORT

Date of I	nspection:	18 12 20 District:	0 1	
Division	: lab	a Cambataba Length Man	Patra	-
Name of	the Road: NO	yatola bodhachak to	5.0	
Scueme/	Programme:	MAINTENANCE Gts ny		haban
Package	No.:	Road Id No.		
Status of	the Project:	Ongoing/Completed/Under Mainter	22000	
	n case of:	New Connectivity/Up gradation/ M	aintenance	
SI. No.	元 学习证	Parameters to be checked	and the first toke the	1 - 16 To Promit 17750
1.	Pavement			Remarks
a)	Road Junction condition			
b)	Condition of S	Irfacing		5
c)				
	Riding Quality			C
d)	Road Camber			
(e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			<
f)	Contraction Joints provided as act (CC Parent)			- (
g)	Compaction of flank/slope & raincuts if any			2
2	Cross Drainage			
a)	Condition of h	ad walls in Hume pipe culverts inc	luding its painting	N/A
b)	Condition of A	butment & Wing walls, Slab in RC	C culverts	MA
c)		ilings/slab/approach for Bridges		NA
3.	Road Furnitu	re .		
	Stolles Paveine	boards/informatory/cautionary B nt road markings are provided and	soard/km & 200m maintained	Yes,
製製	Compliance H	listory =	, Sign	<b>是是就是</b>
a)	Status of ATR	s & any others	* CONTRACTOR ALLEN	S ALTERNATION OF THE PARTY OF T

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	p.20. #

Supriya. 18/12/20, (Signature)

NAME: Supriya Rani

DESIGNATION: Asistant engineer.
Ruod (w) sub olivicion
Sombutdak Patron