

FIELD INSPECTION REPORT

Date of Inspection : 07-01-2021		District : - PARBHANSA	
Division : BEMIDUR		Length (km):	
Name of the Road: SAKETPUR hatia to ulharwari tolg			
Scheme/Programme: MAINTENANCE		M M U S Y	
Package No.:		Road Id No.:	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance			
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	☒ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
07/01/2021
J-E

(Signature)
7/1/2021
AT

(Signature)

NAME: PRADEEP KUMAR

DESIGNATION:- J-E