FIELD INSPECTION REPORT

		FIELD INSPECTION	REPORT	the state of the s	
ole	of Inspection:	18/12/20.	District:	motihani	
reision:		Pakari Jayal.	Length(Km):	d and a second s	
vame of Road:		Pakari Josel Length (Km): Bhaguson pur tola to kalwar			
scheme/Progrmme:		Maintenance			
Package No.		Road Id No.			
Tatus of the Project:		Ongoing/Completed/ Under Maintenance			
Wi	ork is a case of:	New Connectivity/Jpg	and the second s	the comment of the second statement of the second statement of the second secon	
S No.	P:	rameters to be Checcked Remarks			
1	Pavement				
11	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
1)_	Riding Quality			/S/U	
dl	Road Camber		· / S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
1)	Contraction Joints provided or not (CC Pavement)			Yes/No	
(a	Compaction of flank /slope & raincuts if any			/Yes/No	
2	Cross Draina	ge	2 \$65/4V()		
2)	Condition of head	walls in Hume pipe culverts in	ncluding its		
a)	painting	g pipe carrer to mendaning its			
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U S/SRI/U	
<u>c)</u>	Condition of railing /slabs/ approach for Bridges			S/SRI/U	
3	Road Furnitu	ad Furniture			
a)	Whethersign boards/informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			(Yes/No	
3	Complianace History				
a)	Status of ATR's & ar	ny others	The state of the s		
0					
Uvera	Rating:				
		Satisfactory (S) Satisfactory but requires Im Unsatisfactory (II)	provement (SRI)	'5'	
Nan De:	ne:		provement (SRI).		