

FIELD INSPECTION REPORT

Date of Inspection :	8/1/21	District:	Samarthpur
Division :	Samarthpur	Length (km):	0.520
Name of the Road:	To 3 to Simari (Nayajest Vidyalyaga)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	320/0/0/322
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincut if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SSRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SSRIU
c)	Condition of railings/slab/approach for Bridges	✓SSRIU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	NR
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Gautam Das
J.B.


8/1/21
(Signature)