

FIELD INSPECTION REPORT

Date of Inspection :	10/01/2021	District:	Purnia
Division :	Dharrhaha	Length (km)	1.40 km
Name of the Road:	To 5 to Madh Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	/ S/U	
b)	Condition of Surfacing	/ S/U	
c)	Riding Quality	/ S/U	
d)	Road Camber	/ S/U	
e)	Whether free from defects such as visible aggregates in case of CC Pavement.	/ Yes/No	acks, exposed
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No	
g)	Compaction of flank/slope & raincuts if any	/ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts incl	/ S/SRI/U	ing its painting
b)	Condition of Abutment & Wing walls, Slab in RCC	/ S/SRI/U	ulverts
c)	Condition of railings/slab/approach for Bridges	/ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Bo	/ Yes/No	/km & 200m
	stones/Pavement road markings are provided and n		ntained
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

	S
	/

NAME: Shailendra Kumar
 Assistant Engineer.

(Signature) 10/01/21