

FIELD INSPECTION REPORT

MMGSy (GEN)

Date of Inspection :	11-12-2020	District:	Madhyanagar
Division :	Madhyanagar	Length (km):	0.565 Km
Name of the Road:	Madhyanagar PMGSY to Baisia Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31808901225
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>Ongoing</i>
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bipin Kumar
11/12/2020
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.