

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2023	District: Gd. Mahanadi/Boudha
Division : 54438 Boudha	Length (km): 1.7
Name of the Road: Gd. to A. Mahanadi Boudha	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 314788 1001
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flen/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NU

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Babishina Boudha

DESIGNATION: J.C.