

FIELD INSPECTION REPORT

Date of Inspection: - 8/01/2021		District: <u>Nakland</u>	
Division: <u>LC/52</u>		Length (km): - <u>0.886 km</u>	
Name of the Road: - <u>Hetai Rm. Has 6.5 m road to Hiki Pakkam per via vijaygarh</u>			
Scheme/Programme: <u>MAINTENANCE</u>		Road Id No.: <u>MA 914 NO. 8 (BRICK)</u>	
Package No.:			
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>			
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U - S	
b)	Condition of Surfacing	S/U - S	
c)	Riding Quality	S/U - S	
d)	Road Camber	S/U - S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes	
g)	Compaction of flt's/slope & runouts if any	Yes/No Yes	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/ }	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/ } No	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)  08-01-2022 A.E.

NAME: _____