

FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021		District: DARBHANGA	
Division : PENCHUR		Length (km):	
Name of the Road: - KATHANAR SHIBU CHAUDHARY HOUSE TO LAUSMIPUR.			
Scheme/Programme: MAINTENANCE		MMDSY	
Package No.:		Road Id No.:	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ☒
b)	Condition of Surfacing	S/U ☒
c)	Riding Quality	S/U ☒
d)	Road Camber	S/U ☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pradeep Kumar
07/01/2021
J-E

Pharhi
7/1/2021
AE

(Signature)

NAME: PRADEEP KUMAR

DESIGNATION: J-E